



SUGGESTED IPCO FLASHING DETAILS



DO NOT ATTEMPT TO PITCH OR FORM A COVE AT BASE OF FLASHING. THIS CAN IMPAIR PROPER ADHESION OF FLASHING OVERLAP.

THE WRONG WAY



When the flashing membrane bridges the wythes of a cavity wall (or any space), particular care must be taken to prevent mortar droppings from collecting on the flashing. Any weight may cause sagging of the flashing or put undue stress on the sealed laps, which might open and allow water movement. See the IPCO Cavity Bridge data sheet for further information.